2 weeks ago:

Village 3

B1

В9 B10

B17 **B18**

B1

B4

B7

B10

B2

В6

B14

В4 **B3**

B8

B12

B16

B20

B3

B6

B9

B7

B11

B15

B19

Village 6

B₂

B5

B8

WASH Centre: Structural Integrity Index

7.6 7.1 - 7.5 6.6 - 7.0

ВЗ

B7

B11

B19

Village 6

B2

B5

R8

B8

B12

B16

B3

B6

B9

B2

B10

B14

B5 B6

B13

B17 B18

R4

B7

B10

WASH CENTRES

IAP STANDS

**Index Calculation

FORTNIGHTLY WASH CENTRE MONITORING **Azraq Camp**

Overview - Village 3 & Village 6



of active WASH centres: 1505 # of assessed WASH centres*: 1493

Female: 751 #Male: 754 # of active tapstands: 12 # of assessed tapstands: 12 Population Coverage: 14,612

of households: 3,824 # of children: 8.002

WASH CENTRES INDEXES**	This week	2 weeks ago	Trend
Structural Integrity	7.0/8	7.1	•
Child and Disability Access	2.9/4	2.9	*
Hygiene	2.9/4	3.2	•
	_		_
TAP STANDS INDEX**			
Structural Integrity	5.5 / 6	5.7	-

2 weeks ago This week: This Week STRUCTURAL INTEGRITY Doors securely attached to both shower and toilet stalls 1,489 (100%) 1500(100%) 1464 (97%) Door handles attached to both shower and toilet doors 1,456 (98%) 1447 (96%) Locks present on inside of both shower and toilet stalls 1,457 (98%) 1487 (99%) Locks present on outside of both shower and toilet stalls 1,468 (98%) 1441 (96%) There are no holes or tears in the roof of the structure 1444 (97%) 1323 (88%) There are no holes or tears in the walls of the structure 1262 (85%) The desludging cap was present on the desludging pipe and intact 529 (35%) 537 (36%) 1420 (94%) Ventilation pipe is present and fully intact 1396 (94%) This Week 2 weeks ago **ACCESS** Door handles are at a child-friendly height of $(\leq 1.2m)$ 94 (6%) 124 (8%) Outside locks on both doors are at a child-friendly height (≤1.2m) 1,355 (91%) 1330 (88%) Inside locks on both doors are at a child-friendly height of (≤1.2m) 1,465 (98%) 1462 (97%) Both WASH centre doors are not privately locked 1,484 (99%) 1487 (99%) # of WASH centres dedicated to disabled persons 196 (13%) 201 (13%) # of WASH centres with finished access ramp 200 (13%) Disabled toilet is still present in toilets for disabled persons 79 (40%) 105 (52%) This Week 2 weeks ago **CLEANLINESS** 938 (63%) 1010 (67%) There is no rubbish inside both stalls There is no faeces inside both stalls 946 (63%) 1130 (75%) There is no faeces outside the structure within 5m 1026 (69%) There is no standing water outside this structure within 5m 1480 (99%) 1484 (99%)

♣ STRUCTURAL INTEGRITY	This Week	2 weeks ago
The tapstand provides water during its operational hour	s 29 (97%)	30 (100%)
The tapstand has all 4 taps attached	30 (100%)	30 (100%)
Tap handles are present on all remaining taps at the tapstand	23 (77%) >1	%27 (90%)
All remaining taps on the tapstand provide water when turned or	n 23 (100%)-10	%27 (90%)
All remaining taps at the tap stand are protected by tap guard	s 30 (100%)	28 (93%)
The concrete base of the tapstand is in decent shape he status of the concrete tapstand base is judged as "decent" as long as the flow of water is not affected the status of the concrete tapstand base is judged as "decent" as long as the flow of water is not affected the status of the concrete tapstand base is judged as "decent" as long as the flow of water is not affected the status of the concrete tapstand base is judged as "decent" as long as the flow of water is not affected the status of the concrete tapstand base is judged as "decent" as long as the flow of water is not affected the status of the concrete tapstand base is judged as "decent" as long as the flow of water is not affected the status of the concrete tapstand base is judged as "decent" as long as the flow of water is not affected the status of the concrete tapstand base is judged as "decent" as long as the flow of water is not affected the status of the concrete tapstand base is judged as "decent" as long as the flow of water is not affected the status of the concrete tapstand base is judged as "decent" as long as the flow of water is not affected the status of the concrete tapstand base is judged as "decent" as long as the flow of water is not affected the status of the concrete tapstand base is judged as "decent" as long as the flow of the concrete tapstand base is judged as "decent" as long as the flow of the concrete tapstand base is judged as "decent" as long as the flow of the concrete tapstand base is judged as "decent" as long as the flow of the concrete tapstand base is judged as "decent" as long as the flow of the concrete tapstand base is judged as "decent" as long as the flow of the concrete tapstand base is judged as "decent" as long as the flow of the concrete tapstand base is judged as "decent" as long as the flow of the concrete tapstand base is judged as "decent" as long as the flow of the concrete tapstand base is judged as "decent" as long as the flow of the concrete tapstand base is long as the concrete tapstand base is long	у	30 (100%)
OTHER	This Wook	2 weeks ann

There is no faeces on the ground within 10m of this tapstand	30 (100%)	%27 (90%)
# of private hoses connected to individual taps	3	4
Average # of people queuing at the tapstand	2.33	3.27
Flow calculation based on # of seconds it takes to fill a 1L bottle	0.22	0.21

This Week

operational hours

protected by tap guards

decent shape

D. Tapstands – Structural Integrity Index

1. The tapstand provides water during its

The tanstand has all 4 tans attached

5. All remaining taps at the tapstand are

6. The concrete base of the tapstand is in

All remaining taps on the tapstand function i.e. provide water when turned on
 Tap handles are present on all remaining taps at the tapstand

2 weeks ago


A. WASH Centres - Structural Integrity Index
1. Doors securely attached to both shower and toilet


- 2. Door handles attached to both shower and toilet doo Locks present on inside of both shower and toilet stalls
 Locks present on outside of both shower and toilet
- There are no holes or tears in the walls of the structureThe desludging cap was present on the desludging
- Ventilation pipe is present and fully intact


B. WASH Centres - Child Access Index

- Door handles are at a child-friendly height (≤1.2m) . Outside locks on both doors are at a child-friendly height
- Inside locks on both doors are at a child-friendly height
- C. WASH Centres Hygiene Index
 1. There is no rubbish inside both stalls
- There is no faeces inside both stalls 3. There is no faeces outside the structure within 5m
- 4. There is no standing water outside this structure within 5m

Village 3









unicef 🚱



Azraq Camp

Village 3

WASH CENTRES

STANDS

IAP :

**Index Calculation



of active WASH centres: 916 of assessed WASH centres*: 910 # Female: 459 #Male: 457

of active tapstands: 12 # of assessed tapstands: 12 Population Coverage: 6,273

of households: 1,593 # of children: 3,417

This week	2 weeks ago	Trend
7.1 / 8	7.1	*
3.0 / 4	2.9	
2.9/4	3.4	•
	_	
5.4/6	5.8	•
	7.1/8 3.0/4 2.9/4	7.1/8 7.1 3.0/4 2.9 2.9/4 3.4

This Week 2 weeks ago STRUCTURAL INTEGRITY Doors securely attached to both shower and toilet stalls 907 (100%) 913(100%) Door handles attached to both shower and toilet doors 886 (97%) 887 (97%) Locks present on inside of both shower and toilet stalls 881 (97%) 877 (96%) Locks present on outside of both shower and toilet stalls 893 (98%) 907 (99%) 869 (96%) There are no holes or tears in the roof of the structure 871 (95%) There are no holes or tears in the walls of the structure 745 (82%) 804 (88%) 421 (46%) 371 (41%) The desludging cap was present on the desludging pipe and intact 855 (94%) 840 (92%) Ventilation pipe is present and fully intact This Week 2 weeks ago **ACCESS** 83 (9%) Door handles are at a child-friendly height of $(\leq 1.2m)$ 67 (7%) Outside locks on both doors are at a child-friendly height (≤1.2m) 833 (92%) 824 (90%) Inside locks on both doors are at a child-friendly height of (≤1.2m) 890 (98%) 891 (97%) Both WASH centre doors are not privately locked 903 (99%) 901 (99%) # of WASH centres dedicated to disabled persons 140 (15%)

# of WA	SH centres with finished access ramp	134 (15%)	139 (15%)
Disabled toilet is still	present in toilets for disabled persons	58 (43%) >5	% 83 (59%)
CLEANLINESS	Т	his Week	2 weeks ago
CLEANLINESS	There is no rubbish inside both stalls		2 weeks ago 657 (72%)

There is no faeces outside the structure within 5m 642 (71%)

There is no standing water outside this structure within 5m

➡ STRUCTURAL INTEGRITY	This Week	2 weeks ago
The tapstand provides water during its operational hour	rs 12 (100%)	12 (100%)
The tapstand has all 4 taps attached	ed 12 (100%)	12 (100%)
Tap handles are present on all remaining taps at the tapstan	d 8 (67%) >10	%11 (92%)
All remaining taps on the tapstand provide water when turned of	n 12 (100%)	12 (100%)
All remaining taps at the tap stand are protected by tap guard	ls 12 (100%) 10	¹ 10 (83%)
The concrete base of the tapstand is in decent shape *The status of the concrete tapstand base is judged as "decent" as long as the flow of water is not affected		12 (100%)

OTHER 1	his Week	2 weeks ago	
There is no faeces on the ground within 10m of this tapstand	12 (100%)	12 (100%)	
# of private hoses connected to individual taps	0	0	
Average # of people queuing at the tapstand	2.8	7.6	
ow calculation based on # of seconds it takes to fill a 1L bottle	0.18	0.21	

A. WASH Centres - Structural Integrity Index
Doors securely attached to both shower and toile

OTUED

- 2. Door handles attached to both shower and toilet doo Locks present on inside of both shower and toilet stalls
 Locks present on outside of both shower and toilet
- There are no holes or tears in the walls of the structureThe desludging cap was present on the desludging
- 8. Ventilation pipe is present and fully intact

B. WASH Centres - Child Access Index

- . Door handles are at a child-friendly height (<1.2m) Outside locks on both doors are at a child-friendly height
- Inside locks on both doors are at a child-friendly height
- C. WASH Centres Hygiene Index

 1. There is no rubbish inside both stalls
- There is no faeces inside both stalls
- 3. There is no faeces outside the structure within 5m 4. There is no standing water outside this structure within 5m

800 (87%)

908 (99%)

899 (99%)

D. Tapstands - Structural Integrity Index

operational hours

protected by tap guards

decent shape

1. The tapstand provides water during its

The tanstand has all 4 tans attached

5. All remaining taps at the tapstand are


6. The concrete base of the tapstand is in


All remaining taps on the tapstand function, i.e. provide water when turned on
 Arap handles are present on all remaining taps at the tapstand

This week:

2 weeks ago:

Structural Integrity Index





Child and Disability Access Index

Villa	qe 3				Villa	ge 3		
B1	B2	В3	B4	2.6 - 3.0 2.1 - 2.5	B1	B2	В3	B4
B5	B6	В7	В8	1.5 - 2.0	B5	B6	В7	В8
В9	B10	B11	B12		В9	B10	B11	B12
B13	B14	B15	B16		B13	B14	B15	B16
B17	B18	B19	B20		B17	B18	B19	B20
	B1 B5 B9	B5 B6 B9 B10 B13 B14	B1 B2 B3 B5 B6 B7 B9 B10 B11 B13 B14 B15	B1 B2 B3 B4 B5 B6 B7 B8 B9 B10 B11 B12 B13 B14 B15 B16	B1 B2 B3 B4 26-30 21-25	B1 B2 B3 B4 3.1-3.5 (26-3.0) (2.1-2.5	B1 B2 B3 B4 3.1.7.3.5 (26-3.0) (2.1-2.5) (2.1-2	B1 B2 B3 B4 3.1-2.5 2.6 - 3.0 2.1 - 2.5 3.1 - 2







FORTNIGHTLY WASH CENTRE MONITORING **Azraq Camp**

Village 6

WASH CENTRES

TAP STANDS

**Index Calculation



of active WASH centres: 589 of assessed WASH centres*: 583 # Female: 292 #Male: 297

of active tapstands: 12 # of assessed tapstands: 12 Population Coverage: 8,339

of households: 2,231 # of children: 4,585

WASH CENTRES INDEXES**	This week	2 weeks ago	Trend
Structural Integrity	6.9/8	7.0	•
Child and Disability Access	2.9/4	2.9	4
Hygiene	2.9/4	3.0	•
TAP STANDS INDEX**			
Structural Integrity	5.6 / 6	5.6	∢ ₽

This Week 2 weeks ago STRUCTURAL INTEGRITY 587(100%) Doors securely attached to both shower and toilet stalls 582 (100%) 577 (98%) Door handles attached to both shower and toilet doors 570 (98%) 570 (97%) Locks present on inside of both shower and toilet stalls 580 (98%) Locks present on outside of both shower and toilet stalls 575 (98%) 570 (97%) There are no holes or tears in the roof of the structure 575 (98%) 519 (88%) There are no holes or tears in the walls of the structure 517 (89%) The desludging cap was present on the desludging pipe and intact 108 (18%) 166 (28%) 580 (98%) Ventilation pipe is present and fully intact 541 (93%) This Week 2 weeks ago **ACCESS** 27 (5%) 41 (7%) Door handles are at a child-friendly height of $(\leq 1.2m)$ 506 (86%) 575 (98%) 571 (97%) Both WASH centre doors are not privately locked 583 (100%) 584 (99%) # of WASH centres dedicated to disabled persons 61 (10%)

Outside locks on both doors are at a child-friendly height (≤1.2m) Inside locks on both doors are at a child-friendly height of $(\leq 1.2m)$ # of WASH centres with finished access ramp 61 (10%) Disabled toilet is still present in toilets for disabled persons 21 (34%) 22 (36%)

CLEANLINESS	his Week	2 weeks ago
There is no rubbish inside both stalls	403 (69%)>5	×353 (60%)
There is no faeces inside both stalls	344 (59%)>5	407 (69%)
There is no faeces outside the structure within 5m	384 (66%)-5	453 (77%)
There is no standing water outside this structure within 5m	581 (99%)	576 (98%)

D. Tapstands – Structural Integrity Index

operational hours

protected by tap guards 6. The concrete base of the tapstand is in

decent shape

1. The tapstand provides water during its

The tanstand has all 4 tans attached

5. All remaining taps at the tapstand are

All remaining taps on the tapstand function, i.e. provide water when turned on
 Arap handles are present on all remaining taps at the tapstand

➡ STRUCTURAL INTEGRITY	This Week	2 weeks ago
The tapstand provides water during its operational hour	s 17 (94%)	18 (100%)
The tapstand has all 4 taps attache	d 18 (100%)	18 (100%)
Tap handles are present on all remaining taps at the tapstan	d 15 (83%)	16 (89%)
All remaining taps on the tapstand provide water when turned o	n 17 (100%)-1	0%15 (83%)
All remaining taps at the tap stand are protected by tap guard	s 18 (100%)	18 (100%)
The concrete base of the tapstand is in decent shape	* 18 (100%)	18 (100%)
The status of the concrete tapstand base is judged as "decent" as long as the flow of water is not affected any structural dama.		

Official	This Week	2 weeks ago
There is no faeces on the ground within 10m of this tapstand	18 (100%)	¹ 15 (83%)
# of private hoses connected to individual taps	3	4
Average # of people queuing at the tapstand	1 2	0.39
Flow calculation based on # of seconds it takes to fill a 1L bottle	0.25	0.22

A. WASH Centres - Structural Integrity Index

OTHER


- 2. Door handles attached to both shower and toilet doo Locks present on inside of both shower and toilet stalls
 Locks present on outside of both shower and toilet
- 5. There are no holes or tears in the roof of the structure There are no holes or tears in the walls of the structureThe desludging cap was present on the desludging
- Ventilation pipe is present and fully intact
- B. WASH Centres Child Access Index
- . Door handles are at a child-friendly height (<1.2m) 2. Outside locks on both doors are at a child-friendly height
- Inside locks on both doors are at a child-friendly height
- C. WASH Centres Hygiene Index


 1. There is no rubbish inside both stalls
- There is no faeces inside both stalls
- 3. There is no faeces outside the structure within 5m 4. There is no standing water outside this structure within 5m

This week:


2 weeks ago:

Structural Integrity Index





Child and Disability Access Index









FORTNIGHTLY WASH CENTRE MONITORING Azraq Camp

Map 1: Faeces found inside WASH centres in Village 3





Map 2: Faeces found inside WASH centres in Village 6





Map 3: Faeces found outside WASH centres in Village 3







Map 4: Faeces found outside WASH centres in Village 6










FORTNIGHTLY WASH CENTRE MONITORING Azraq Camp

Map 5: Outside locks at the height of 1.2m from the ground or lower in Village 3





Map 6: Outside locks at the height of 1.2m from the ground or lower in Village 6







FORTNIGHTLY WASH CENTRE MONITORING Azraq Camp

Map 7: Missing tapstand handles and private connections in Village 3



Map 8: Missing tapstand handles and private connections in Village 6



